

- Disjoncteur
- Circuit breakers
- Leistungsschalter
- Interruptores
- Interruttori
- Disjuntor
- αυτόματη ασφάλεια
- Wyłącznik
- Devre kesici

DPX 1250 DPX 1600 DPX-I 1600

NT 80040LC

	3P	3P DPX I	4P	4P DPX I
A	-	-	1	1
B	1	1	-	-
C	2	2	3	3
D	-	-	2	2
E	2	2	-	-
F	6	6	8	8
G	12	12	16	16
H	1	-	1	-
I	2	2	-	-
L	-	-	2	2
M	4	4	4	4

2

- 1) Manette de commande
- 2) Bouton de test mécanique
- 3) Réglage des déclencheur

- 1) Operating handle
- 2) Push-to-trip button for mechanical checking
- 3) Setting of releases

- 1) Betätigungshebel
- 2) Prüftaste für mechanische Kontrolle
- 3) Einstellung

- 1) Maneta de accionamiento
- 2) Pulsador de prueba para la verificación mecánica
- 3) Regulación

- 1) Leva di comando
- 2) Tasto di prova meccanica
- 3) Regolazione

- 1) Manete de comando
- 2) Botão de teste mecânico
- 3) Regulação

- 1) Μοχλός χειρισμών
- 2) Μπουτόν για μηχανικό έλεγχο
- 3) Ρύθμιση θερμικών στοιχείων

- 1) Dźwignia załączająca
- 2) Przycisk testu mechanicznego
- 3) Regulacja wyzwalaczy

- 1) Kumanda kolu
- 2) Mekanik test düğmesi
- 3) Açma ayarı

1

	3P	4P
A	210	280
B	70	-
C	-	140

	S
DPX 1250 ≥ 1000 A	12
DPX 1600ES ≥ 1000 A	
DPX-I 1600 ≥ 1000 A	
DPX 1250 < 1000 A	8
DPX 1600 < 1000 A	
DPX-I 1600 < 1000 A	

3

MAX 50x10

ø 14

MAX 23

M12

F 25 Nm

